






- 

**1** Insert the thread spool onto the spool pin and secure it with a spool cap **1**.
- 

**2** While holding the thread near the spool, draw the end of the thread around the upper thread guide **2** to then down around the check spring holder **3**.
- 

**3** Firmly draw the thread up from right to left over the take-up lever **4**, and down into the take-up lever eye.
- 

**4** Pass the thread through the lower thread guide **5**. Slide the thread behind the needle bar thread guide on the left.
- 

**5** Thread the needle from front to back **6**, or use the needle threader.

# MACHINE THREADING